



Leader Tech Inc.

59-CBSA-3.0X5.25X0.5

Tau Wae:	59-CBSA-3.0X5.25X0.5
Kaihanga / Waitohu:	Leader Tech Inc.
Whakaahuatanga hua	59 SERIES CBS SHIELD ASSEMBLY - 1.59-CBSA-3.0X5.25X0.5.pdf 2.59-CBSA-3.0X5.25X0.5.pdf
Ngā Rauemi:	Whakahaerehia te kore utu / RoHS
RoHs Tūnga	3836 pcs stock
Waehe Stock	Hong Kong
Tuhinga mai i	DHL/Fedex/TNT/UPS/EMS
Te Ara Tuhi	

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 59-CBSA-3.0X5.25X0.5

TAU WAE	59-CBSA-3.0X5.25X0.5
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	59 SERIES CBS SHIELD ASSEMBLY -
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	3836 pcs
PEPA RARAUNGA	1.59-CBSA-3.0X5.25X0.5.pdf 2.59-CBSA-3.0X5.25X0.5.pdf
WHĀNUI - WHĀNUI	3.000" (76.20mm)
TUHINGA O MUA	Vent Holes in Pattern
MOMO	Shield, 2-Piece
RAUPAPA	50-CBS
PACKAGING	Bulk
ĒTAHI INGOA	59-CBSA-3.0X5.25X0.4 59-CBSA-3.0X5.25X0.4-ND
MOMO TAE	Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE ROA - WHĀNUI	5.250" (133.35mm)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TEITEI - WHĀNUI	0.500" (12.70mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 3.000" (76.20mm) X 5.250" (133.35mm) Vent Holes in Pattern Through Hole

Ngā tūtohu e hāngai ana

Leader Tech Inc. 59-CBSA-3.0X5.25X0.5	59-CBSA-3.0X5.25X0.5 Kaiwhiwhi	59-CBSA-3.0X5.25X0.5 Kaiwhakarato
59-CBSA-3.0X5.25X0.5 Utu	59-CBSA-3.0X5.25X0.5 Pikitia	59-CBSA-3.0X5.25X0.5 Whakaahua
59-CBSA-3.0X5.25X0.5 PDF Datasheet	59-CBSA-3.0X5.25X0.5 Download Datasheet	Tuhinga 59-CBSA-3.0X5.25X0.5
59-CBSA-3.0X5.25X0.5 Stock	Hokona 59-CBSA-3.0X5.25X0.5	Hokona Leader Tech Inc. 59-CBSA-3.0X5.25X0.5
Leader Tech Inc. 59-CBSA-3.0X5.25X0.5	Leader Tech Inc. Kaiwhakarato	Leader Tech Inc. Kaiwhiwhi
Leader Tech Inc. 59-CBSA-3.0X5.25X0.5		

Ngā Hua e hāngai ana

<p>59-CBSA-3.0X4.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4725 pcs</p> <p>RFQ</p>	<p>59-CBSA-3.0X6.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3559 pcs</p> <p>RFQ</p>
<p>59-CBSA-3.0X5.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3603 pcs</p> <p>RFQ</p>	<p>59-CBSA-3.25X3.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4070 pcs</p> <p>RFQ</p>
<p>59-CBSA-3.0X5.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3811 pcs</p> <p>RFQ</p>	<p>59-CBSA-3.0X4.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3978 pcs</p> <p>RFQ</p>
<p>59-CBSA-3.0X5.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4007 pcs</p> <p>RFQ</p>	<p>59-CBSA-3.0X3.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4068 pcs</p> <p>RFQ</p>
<p>59-CBSA-3.0X4.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3563 pcs</p> <p>RFQ</p>	<p>59-CBSA-3.0X4.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4046 pcs</p> <p>RFQ</p>
<p>59-CBSA-3.25X3.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4175 pcs</p> <p>RFQ</p>	<p>59-CBSA-3.25X3.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4359 pcs</p> <p>RFQ</p>