



14R-CBSA-0.75X2.75X0.13

| | |
|---------------------|----------------------------------|
| Tau Wae: | 14R-CBSA-0.75X2.75X0.13 |
| Kaihanga / Waitohu: | Leader Tech Inc. |
| Whakaahuatanga hua | 14R SERIES CBS SHIELD ASSEMBLY - |
| Ngā Rauemi: | 14R-CBSA-0.75X2.75X0.13.pdf |
| RoHS Tūnga | Whakahaerehia te kore utu / RoHS |
| Waehere Stock | 4681 pcs stock |
| Tuhinga mai i | Hong Kong |
| Te Ara Tuhi | DHL/Fedex/TNT/UPS/EMS |

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 14R-CBSA-0.75X2.75X0.13

| | |
|---|--|
| TAU WAE | 14R-CBSA-0.75X2.75X0.13 |
| KAIHANGA | Leader Tech Inc. |
| WHAKAAHUATANGA | 14R SERIES CBS SHIELD ASSEMBLY - |
| WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA | Whakahaerehia te kore utu / RoHS |
| HE RAHINGA KEI TE WĀTEA | 4681 pcs |
| PEPA RARAUNGA | 14R-CBSA-0.75X2.75X0.13.pdf |
| WHĀNUI - WHĀNUI | 0.750" (19.05mm) |
| TUHINGA O MUA | Vent Holes in Pattern |
| MOMO | Shield, 2-Piece |
| RAUPAPA | 10-CBS |
| PACKAGING | Bulk |
| MOMO TAE | Through Hole |
| TAUMATA WHAKAARO MOE (MSL) | 1 (Unlimited) |
| TE ROA - WHĀNUI | 2.750" (69.85mm) |
| WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA | Lead free / RoHS Compliant |
| TEITEI - WHĀNUI | 0.130" (3.30mm) |
| WHAKAAHUATANGA TAIPITOPITO | RF Shield Shield, 2-Piece 0.750" (19.05mm) X 2.750" (69.85mm) Vent Holes in Pattern Through Hole |

Ngā tūtohu e hāngai ana

| | | |
|--|--|---|
| Leader Tech Inc. 14R-CBSA-0.75X2.75X0.13 | 14R-CBSA-0.75X2.75X0.13 Kaihiwhi | 14R-CBSA-0.75X2.75X0.13 Kaiwhakarato |
| 14R-CBSA-0.75X2.75X0.13 Utu | 14R-CBSA-0.75X2.75X0.13 Pikitia | 14R-CBSA-0.75X2.75X0.13 Whakaahua |
| 14R-CBSA-0.75X2.75X0.13 PDF Datasheet | 14R-CBSA-0.75X2.75X0.13 Download Datasheet | Tuhinga 14R-CBSA-0.75X2.75X0.13 |
| 14R-CBSA-0.75X2.75X0.13 Stock | Hokona 14R-CBSA-0.75X2.75X0.13 | Hokona Leader Tech Inc. 14R-CBSA-0.75X2.75X0.13 |
| Leader Tech Inc. 14R-CBSA-0.75X2.75X0.13 | Leader Tech Inc. Kaiwhakarato | Leader Tech Inc. Kaihiwhi |
| Leader Tech Inc. 14R-CBSA-0.75X2.75X0.13 | | |

Ngā Hua e hāngai ana

| | |
|---|---|
| <p>14R-CBSA-0.75X4.0X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 14R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4219 pcs</p> <p>RFQ</p> | <p>14R-CBSA-0.75X2.5X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 14R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4170 pcs</p> <p>RFQ</p> |
| <p>14R-CBSA-0.75X4.25X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 14R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4038 pcs</p> <p>RFQ</p> | <p>14R-CBSA-0.75X3.5X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 14R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4964 pcs</p> <p>RFQ</p> |
| <p>14R-CBSA-0.75X3.75X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 14R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4078 pcs</p> <p>RFQ</p> | <p>14R-CBSA-0.75X3.25X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 14R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4375 pcs</p> <p>RFQ</p> |
| <p>14R-CBSA-0.75X3.0X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 14R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3990 pcs</p> <p>RFQ</p> | <p>14R-CBSA-0.75X1.25X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 14R-CBSA-0.75X1.25X0.13--14R341- I roto i te taonga: 5522 pcs</p> <p>RFQ</p> |
| <p>14R-CBSA-0.75X1.5X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 14R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5557 pcs</p> <p>RFQ</p> | <p>14R-CBSA-0.75X2.25X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 14R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4947 pcs</p> <p>RFQ</p> |
| <p>14R-CBSA-0.75X1.75X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 14R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4192 pcs</p> <p>RFQ</p> | <p>14R-CBSA-0.75X2.0X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 14R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5092 pcs</p> <p>RFQ</p> |