



Micrel / Microchip Technology

SY89809LTC

Tau Wae:

SY89809LTC

Kaihanga / Waitohu:

Micrel / Microchip Technology

Whakaahuatanga hua

IC CLK BUFFER 2:9 500MHZ 32TQFP

Ngā Rauemi:

 SY89809LTC.pdf

RoHS Tūnga

 Kei roto nga rangatira / RoHS kaore i te ture

Waeheere Stock

13465 pcs stock

Tuhinga mai i

Hong Kong


Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













Ngā whakaaturanga o SY89809LTC

TAU WAE	SY89809LTC
KAIHANGA	Micrel / Microchip Technology
WHAKAAHUATANGA	IC CLK BUFFER 2:9 500MHZ 32TQFP
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Kei roto nga rangatira / RoHS kaore i te ture
HE RAHINGA KEI TE WĀTEA	13465 pcs
PEPA RARAUNGA	 SY89809LTC.pdf
TUHINGA O MUA	3 V ~ 3.6 V
MOMO	Fanout Buffer (Distribution), Multiplexer
PŪRERE PŪRERE WHAKARATO	32-TQFP (7x7)
RAUPAPA	Precision Edge®
RATONGA - WHAKAURU: WHAKAPUTA	2:9
PACKAGING	Tray
PAA / CASE	32-TQFP
WHAKAPUTA	HSTL
TAE MAHI	0°C ~ 85°C
TUHINGA O MUA	1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Contains lead / RoHS non-compliant
WHAKAURU	HSTL, LVPECL
TAUTANGA - MAX	500MHz
MOTUHAKE - WHAKAURU: WHAKAPUTA	Yes/Yes
WHAKAAHUATANGA TAIPITOPITO	Clock Fanout Buffer (Distribution), Multiplexer IC 2:9 500MHz 32-TQFP
TAU WAE TUAKIRI	SY89809

Ngā tūtohu e hāngai ana

Micrel / Microchip Technology SY89809LTC	SY89809LTC Kaiwhiwhi	SY89809LTC Kaiwhakarato
SY89809LTC Utu	SY89809LTC Pikitia	SY89809LTC Whakaahua
SY89809LTC PDF Datasheet	SY89809LTC Download Datasheet	Tuhinga SY89809LTC
SY89809LTC Stock	Hokona SY89809LTC	Hokona Micrel / Microchip Technology SY89809LTC
Micrel / Microchip Technology SY89809LTC	Micrel / Microchip Technology Kaiwhakarato	Micrel / Microchip Technology Kaiwhiwhi
Micrel / Microchip Technology SY89809LTC	Microchip Technology SY89809LTC	Roving Networks / Microchip Technology SY89809LTC

Ngā Hua e hāngai ana

 <p>SY89809ALTZ Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:9 750MHZ 32TQFP I roto i te taonga: 12731 pcs</p> <p>RFQ</p>	 <p>SY89809LTH-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:9 500MHZ 32TQFP I roto i te taonga: 4679 pcs</p> <p>RFQ</p>
 <p>SY89809ALTH Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:9 750MHZ 32TQFP I roto i te taonga: 11740 pcs</p> <p>RFQ</p>	 <p>SY89808LTI Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:9 500MHZ 32TQFP I roto i te taonga: 12993 pcs</p> <p>RFQ</p>
 <p>SY89809LTH Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:9 500MHZ 32TQFP I roto i te taonga: 7095 pcs</p> <p>RFQ</p>	 <p>SY89809LTC-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:9 500MHZ 32TQFP I roto i te taonga: 19165 pcs</p> <p>RFQ</p>
 <p>SY89823LHI Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:22 500MHZ 64TQFP I roto i te taonga: 6167 pcs</p> <p>RFQ</p>	 <p>SY89823LHI-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:22 500MHZ 64TQFP I roto i te taonga: 8403 pcs</p> <p>RFQ</p>
 <p>SY89808LTI-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:9 500MHZ 32TQFP I roto i te taonga: 15667 pcs</p> <p>RFQ</p>	 <p>SY89823LHG Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:22 500MHZ 64TQFP I roto i te taonga: 6761 pcs</p> <p>RFQ</p>
 <p>SY89809ALTZ-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:9 750MHZ 32TQFP I roto i te taonga: 10226 pcs</p> <p>RFQ</p>	 <p>SY89809ALTH TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:9 750MHZ 32TQFP I roto i te taonga: 15558 pcs</p> <p>RFQ</p>