




Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

AMS22S5A1BLAFL133

Tau Wae:	AMS22S5A1BLAFL133
Kaihanga / Waitohu:	Bourns, Inc.
Whakaahuatanga hua	SENSOR ROTARY 330DEG SOLDER LUG
Ngā Rauemi:	AMS22S5A1BLAFL133.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waehere Stock	2083 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ngā whakaaturanga o AMS22S5A1BLAFL133

TAU WAE	AMS22S5A1BLAFL133
KAIHANGA	Bourns, Inc.
WHAKAAHUATANGA	SENSOR ROTARY 330DEG SOLDER LUG
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	2083 pcs
PEPA RARAUNGA	AMS22S5A1BLAFL133.pdf
TUHINGA O MUA	5V
KĀHUA WHAKAMUTUNGA	Solder Lug
HANGARAU	Hall Effect
PŪRERE PŪRERE WHAKARATO	-
RAUPAPA	AMS22S
MAHINGA WHAKATERE - HANGARAU, HANGARAU	10° ~ 330°, Continuous
TE TANGATA TANGATA	-
PACKAGING	Bulk
PAA / CASE	Module, Flatted Shaft
WAITOHU WHAKAPUTA	Counterclockwise Increase
WHAKAPUTA	Analog Voltage
TAE MAHI	-40°C ~ 125°C
MOMO TAE	Panel Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TUHINGA	±0.5%
RAINA RAINA	-
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
MO TE INE	Rotary Position
WHAKAAHUATANGA TAIPITOPITO	Hall Effect Sensor Rotary Position Flatted Shaft Solder Lug
MOMO KAIHOKO	Flatted Shaft

Ngā tūtohu e hāngai ana

Bourns, Inc. AMS22S5A1BLAFL133	AMS22S5A1BLAFL133 Kaiwhiwhi	AMS22S5A1BLAFL133 Kaiwhakarato
AMS22S5A1BLAFL133 Utu	AMS22S5A1BLAFL133 Pikitia	AMS22S5A1BLAFL133 Whakaahua
AMS22S5A1BLAFL133 PDF Datasheet	AMS22S5A1BLAFL133 Download Datasheet	Tuhinga AMS22S5A1BLAFL133
AMS22S5A1BLAFL133 Stock	Hokona AMS22S5A1BLAFL133	Hokona Bourns, Inc. AMS22S5A1BLAFL133
Bourns, Inc. AMS22S5A1BLAFL133	Bourns, Inc. Kaiwhakarato	Bourns, Inc. Kaiwhiwhi
Bourns, Inc. AMS22S5A1BLAFL133	Bourns Inc. AMS22S5A1BLAFL133	J.W. Miller / Bourns AMS22S5A1BLAFL133

Ngā Hua e hāngai ana

AMS22S5A1BLAFL1BB Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 45DEG SOLDER LUG I roto i te taonga: 2218 pcs RFQ	AMS22S5A1BLAFL136 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 360DEG SOLDER LUG I roto i te taonga: 1749 pcs RFQ
AMS22S5A1BLAFL127 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 270DEG SOLDER LUG I roto i te taonga: 1989 pcs RFQ	AMS22S5A1BLAFL128 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 280DEG SOLDER LUG I roto i te taonga: 2109 pcs RFQ
AMS22S5A1BLAFL130 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 300DEG SOLDER LUG I roto i te taonga: 2250 pcs RFQ	AMS22S5A1BLAFL302 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 20DEG SOLDER LUG I roto i te taonga: 1806 pcs RFQ
AMS22S5A1BLAFL134 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 340DEG SOLDER LUG I roto i te taonga: 1965 pcs RFQ	AMS22S5A1BLAFL131 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 310DEG SOLDER LUG I roto i te taonga: 2070 pcs RFQ
AMS22S5A1BLAFL132 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 320DEG SOLDER LUG I roto i te taonga: 1992 pcs RFQ	AMS22S5A1BLAFL129 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 290DEG SOLDER LUG I roto i te taonga: 2298 pcs RFQ
AMS22S5A1BLAFL135 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 350DEG SOLDER LUG I roto i te taonga: 2171 pcs RFQ	AMS22S5A1BLAFL301 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 10DEG SOLDER LUG I roto i te taonga: 2110 pcs RFQ