



## 18R-CBSA-1.0X6.0X0.13

Tau Wae:	18R-CBSA-1.0X6.0X0.13
Kaihanga / Waitohu:	Leader Tech Inc.
Whakaahuatanga hua	18R SERIES CBS SHIELD ASSEMBLY -
Ngā Rauemi:	18R-CBSA-1.0X6.0X0.13.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waehere Stock	3704 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

### Ngā whakaaturanga o 18R-CBSA-1.0X6.0X0.13

TAU WAE	18R-CBSA-1.0X6.0X0.13
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	18R SERIES CBS SHIELD ASSEMBLY -
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	3704 pcs
PEPA RARAUNGA	18R-CBSA-1.0X6.0X0.13.pdf
WHĀNUI - WHĀNUI	1.000" (25.40mm)
TUHINGA O MUA	Vent Holes in Pattern
MOMO	Shield, 2-Piece
RAUPAPA	10-CBS
PACKAGING	Bulk
MOMO TAE	Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE ROA - WHĀNUI	6.000" (152.40mm)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TEITEI - WHĀNUI	0.130" (3.30mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 1.000" (25.40mm) X 6.000" (152.40mm) Vent Holes in Pattern Through Hole

### Ngā tūtohu e hāngai ana

Leader Tech Inc. 18R-CBSA-1.0X6.0X0.13	18R-CBSA-1.0X6.0X0.13 Kaiwhiwhi	18R-CBSA-1.0X6.0X0.13 Kaiwhakarato
18R-CBSA-1.0X6.0X0.13 Utu	18R-CBSA-1.0X6.0X0.13 Pikitia	18R-CBSA-1.0X6.0X0.13 Whakaahua
18R-CBSA-1.0X6.0X0.13 PDF Datasheet	18R-CBSA-1.0X6.0X0.13 Download Datasheet	Tuhinga 18R-CBSA-1.0X6.0X0.13
18R-CBSA-1.0X6.0X0.13 Stock	Hokona 18R-CBSA-1.0X6.0X0.13	Hokona Leader Tech Inc. 18R-CBSA-1.0X6.0X0.13
Leader Tech Inc. 18R-CBSA-1.0X6.0X0.13	Leader Tech Inc. Kaiwhakarato	Leader Tech Inc. Kaiwhiwhi
Leader Tech Inc. 18R-CBSA-1.0X6.0X0.13		

### Ngā Hua e hāngai ana

<p><b>18R-CBSA-1.25X2.5X0.13</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 18R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4627 pcs</p> <p><b>RFQ</b></p>	<p><b>18R-CBSA-1.0X5.0X0.13</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 18R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4822 pcs</p> <p><b>RFQ</b></p>
<p><b>18R-CBSA-1.25X2.0X0.13</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 18R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5065 pcs</p> <p><b>RFQ</b></p>	<p><b>18R-CBSA-1.0X4.5X0.13</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 18R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4673 pcs</p> <p><b>RFQ</b></p>
<p><b>18R-CBSA-1.25X1.5X0.13</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 18R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 6174 pcs</p> <p><b>RFQ</b></p>	<p><b>18R-CBSA-1.25X1.25X0.13</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 18R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5976 pcs</p> <p><b>RFQ</b></p>
<p><b>18R-CBSA-1.0X5.5X0.13</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 18R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4128 pcs</p> <p><b>RFQ</b></p>	<p><b>18R-CBSA-1.25X1.75X0.13</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 18R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5864 pcs</p> <p><b>RFQ</b></p>
<p><b>18R-CBSA-1.0X5.75X0.13</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 18R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3521 pcs</p> <p><b>RFQ</b></p>	<p><b>18R-CBSA-1.0X5.25X0.13</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 18R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3817 pcs</p> <p><b>RFQ</b></p>
<p><b>18R-CBSA-1.25X2.25X0.13</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 18R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5416 pcs</p> <p><b>RFQ</b></p>	<p><b>18R-CBSA-1.0X4.75X0.13</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 18R SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4566 pcs</p> <p><b>RFQ</b></p>