

crydom

Crydom

HD4875

Tau Wae: HD4875

Kaihanga / Waitohu: Crydom

Whakaahuatanga hua: SSR RELAY SPST-NO 75A 48-530V

Ngā Rauemi:

1.HD4875.pdf

2.HD4875.pdf

3.HD4875.pdf

RoHS Tūnga

Whakahaerehia te kore utu / RoHS

Waehe Stock

835 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o HD4875

TAU WAE	HD4875
KAIHANGA	Crydom
WHAKAAHUATANGA	SSR RELAY SPST-NO 75A 48-530V
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	835 pcs
PEPA RARAUNGA	1.HD4875.pdf 2.HD4875.pdf 3.HD4875.pdf
NGAOHIHI - TAE	48V ~ 530V
MOMOTUHI - WHAKAURU	3 ~ 32VDC
KĀHUA WHAKAMUTUNGA	Screw Terminal
PŪRERE PŪRERE WHAKARATO	-
RAUPAPA	HD48
PACKAGING	Bulk
PAA / CASE	Hockey Puck
MOMO PUTANGA	AC, Zero Cross
ĒTAHI INGOA	CC1020
MOMO TAE	Chassis Mount
TAUMAHI KAUTE	75A
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAAHUATANGA TAIPITOPITO	Solid State Relay SPST-NO (1 Form A) Hockey Puck
TAKAHANGA	SPST-NO (1 Form A)

Ngā tūtohu e hāngai ana

Crydom HD4875	HD4875 Kaiwhiwhi	HD4875 Kaiwhakarato
HD4875 Utu	HD4875 Pikitia	HD4875 Whakaahua
HD4875 PDF Datasheet	HD4875 Download Datasheet	Tuhinga HD4875
HD4875 Stock	Hokona HD4875	Hokona Crydom HD4875
Crydom HD4875	Crydom Kaiwhakarato	Crydom Kaiwhiwhi
Crydom HD4875	AMI SEMICONDUCTOR HD4875	Crydom Co. HD4875
Sensata Technologies – Crydom HD4875		

Ngā Hua e hāngai ana

<p>HD4850P Kaihanga: Crydom Whakaahuatanga: RELAY SSR 530VAC/50A DC I roto i te taonga: 1494 pcs</p> <p>RFQ</p>	<p>HD4875G Kaihanga: Crydom Whakaahuatanga: RELAY SSR 530VAC/75A DC I roto i te taonga: 918 pcs</p> <p>RFQ</p>
<p>HD4875-10 Kaihanga: Crydom Whakaahuatanga: SSR RELAY SPST-NO 75A 48-530V I roto i te taonga: 1004 pcs</p> <p>RFQ</p>	<p>HD4875G-10 Kaihanga: Crydom Whakaahuatanga: RELAY SSR 530VAC/75A DC I roto i te taonga: 894 pcs</p> <p>RFQ</p>
<p>HD4850PGHT Kaihanga: Crydom Whakaahuatanga: RELAY SSR 530VAC/50A DC I roto i te taonga: 1090 pcs</p> <p>RFQ</p>	<p>HD4875K-10 Kaihanga: Crydom Whakaahuatanga: RELAY SSR 530VAC/75A DC I roto i te taonga: 1090 pcs</p> <p>RFQ</p>
<p>HD4850T Kaihanga: Crydom Whakaahuatanga: RELAY SSR 530VAC/50A DC I roto i te taonga: 1736 pcs</p> <p>RFQ</p>	<p>HD4850S Kaihanga: Crydom Whakaahuatanga: RELAY SSR 530VAC/50A DC I roto i te taonga: 1569 pcs</p> <p>RFQ</p>
<p>HD4890 Kaihanga: Crydom Whakaahuatanga: SSR RELAY SPST-NO 90A 48-530V I roto i te taonga: 959 pcs</p> <p>RFQ</p>	<p>HD4875KT-10 Kaihanga: Crydom Whakaahuatanga: RELAY SSR 530VAC/75A DC I roto i te taonga: 1072 pcs</p> <p>RFQ</p>
<p>HD4850PGH Kaihanga: Crydom Whakaahuatanga: RELAY SSR 530VAC/50A DC I roto i te taonga: 1107 pcs</p> <p>RFQ</p>	<p>HD4850KT-10 Kaihanga: Crydom Whakaahuatanga: RELAY SSR 530VAC/50A DC I roto i te taonga: 1368 pcs</p> <p>RFQ</p>